PROJECT NEEDS

Structural Deficiencies of the Bridge

- ► The bridge deck is cracking throughout
- ► The superstructure exhibits cracking, spalling, and exposed corroded rebar
- The sidewalk has broken sections and is uneven throughout
- ► Water infiltrating cracks and joints in the bridge has caused damage or failure of various structural components
- ► The bridge barriers do not meet current crash requirements
- ► Arch span columns and beams have reduced support for the bridge deck





Inefficient Movements at Western Approach Intersection in Wrightsville Borough

- ► Unusual 5-point intersection
- ► Bicycle and pedestrian movements at the intersection are substandard (excessive length, lack of markings, no traffic control devices)
- Select turning movements at the intersection are prohibited
- ► Sight distances for various user modes is limited



Inadequate Bicycle and Pedestrian Mobility in Project Corridor

- ► Currently no bike lanes exist to delineate and limit interactions between cyclists and non-cyclists
- ► There is lack of adequate markings and signage directing pedestrians and cyclists to riverfront trails and parks on both sides of the bridge







