


state college area CONNECTOR



- ① PEL corridor was further south of US 322 in the east. The current alignment shifts north of existing US 322 to minimize effects to farm operations and other environmental features south of US 322.
- ② Removed the interchange.



South Alternative vs. US 322-5 PEL Corridor